



PATENT

**Certificate**  
**JUN 30 2004**  
**of Correction**

Attorney Docket No. 9281-7

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re: Shefet et al.

U.S. Patent No.: 6,713,107

Application Serial No.: 10/087,548

Issued: March 30, 2004

Filed: March 1, 2002

For: AIRFLOW DISTRIBUTION SYSTEMS FOR FOOD PROCESSORS

Date: June 23, 2004

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION UNDER  
35 U.S.C §254 AND 37 C.F.R. §1.322**

Sir:

The Assignee of record for the above-referenced patent hereby requests, pursuant to 35 U.S.C §254 and 37 C.F.R. §1.322, that a Certificate of Correction be issued. This request is made in order to correct the mistakes incurred through the fault of the U.S. Patent and Trademark Office. No fee is believed due. However, the Commissioner is authorized to charge any deficiency or credit any overpayment to Deposit Account No. 50-0220.

The mistakes appearing in the patent are set forth with corrections on the Certificate of Correction enclosed herewith, with an additional copy thereof and a return post card.

Respectfully submitted,




Julie H. Richardson  
Registration No. 40,142

Myers Bigel Sibley & Sajovec, P.A.  
P. O. Box 37428  
Raleigh, North Carolina 27627  
Telephone: (919) 854-1400  
Facsimile: (919) 854-1401  
Customer No. 20792

**Certificate of Mailing under 37 CFR 1.8**

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on June 23, 2004.

  
Evelyn B. Casey

**BEST AVAILABLE COPY 1 JUL 2004**

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,713,107  
DATED : March 30, 2004  
INVENTOR(S) : Shefet et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE CLAIMS

Column 19, line 58 (Claim 1) should read as follows:

-- side **portion** of the travel pathway during the moving --

Column 24, line 18 (Claim 55) should read as follows:

- - wherein the **gas** distribution system is configured to - -

MAILING ADDRESS OF SENDER:  
Myers, Bigel, Sibley & Sajovec  
P.O. Box 37428  
Raleigh, NC 27627

PATENT NO. 6,713,107

No. of additional copies: \_\_\_\_\_



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

BEST AVAILABLE COPY

1 JUL 2004